PHASE 1 ENVIRONMENTAL REPORT of a site at 219-223 COLDHARBOUR LANE, BRIXTON, LAMBETH, LONDON, SW9 8RU for COLDHARBOUR LANE LTD

Contaminated Land Solutions

4 De Frene Rd, London, SE26 4AB t: 020 8291 1354, e: ask@gosolve.co.uk

Project No 0973 Report ref: 0973-P1E-1 Issued: July 2016

Revision:

CONTENTS

- 1 EXECUTIVE SUMMARY
- 2 BRIEF
- 3 SITE VISIT
- 4 SITE LOCATION
- 5 SITE DESCRIPTION
- 6 GROUND CONDITIONS
 - 6.1 Geology
 - 6.2 Hydrogeology
 - 6.3 Hydrology
 - 6.4 Ground Stability Hazards
 - 6.5 Mining Activities
 - 6.6 Radon Gas
 - 6.7 Sensitive Land Use
- 7 SITE HISTORY
- 8 PROPOSED DEVELOPMENT
- 9 POTENTIAL CONTAMINATION
 - 9.1 General
 - 9.2 Off Site Contamination
 - 9.3 On Site Contamination
 - 9.4 Preliminary Conceptual Model
- 10 RISK ASSESSMENT
- 11 SITE WORK
 - 11.1 Investigations
 - 11.2 Site Preparation
 - 11.3 External Works
- 12 SITE DEVELOPMENT CONSIDERATIONS
- 13 CONCLUSIONS
 - Appendix A Site Location Plan
 - Appendix B Proposed Site Plan
 - Appendix C Photographs
 - Appendix D Landmark Report Extracts
 - **Appendix E Historical Maps**
 - **Appendix F Owner's Information**
 - Appendix G Contacts
 - Appendix H References

1 EXECUTIVE SUMMARY

Details	Summary of Ma	nin Text		
Proposed Development	Retail, offices an	Retail, offices and residential without soft landscaping		
Current Site Use		cently various commercial including a crash entre & car wash		
Site History		ing shows phases of redevelopment and om initially residential scale properties.		
Surrounding Area		cial use, retail, vehicle repairs and the h some residential		
Environmental Setting		Superficial: NA Bedrock: London Clay Formation		
Cotting	Hydrogeology E	Superficial: NA Bedrock: Unproductive Non-Aquifer Source Protection Zone: NA		
Potential Contamination Sources	The site walkover, historical mapping and environmental searches have identified the following potential sources of contamination. • Site use as crash damage repair centre & car wash • Hard core & demolition debris within the made ground • Nearby vehicle repair workshop, railway & scrap metal dealer • Naturally occurring contaminants			
Risk Assessment Findings	Risk ratings of moderate or greater indicate potential complete source-pathway-receptor linkages that can require further investigation and remedial measures. The following moderate or greater risks have been identified at the site. Site users drinking of water from supply impacted contaminated soil Workers in dermal contact or ingesting contaminate soil Workers inhaling contaminated dust Sulphates in contact with building materials Site workers inhaling fibres (asbestos) Some preliminary intrusive environmental site investigating is recommended to determine if contamination is present the property. This report is provided to the water supplier with a require for the testing, if any, that they require. It is considered that provided the recommendations of the report are implemented there is no increased risk to hum health from redevelopment of the site for the proposed use			
Recommendations				

Risk Summary

Very	Low	Moderate /	Moderate	High
Low	Low	Low	Moderate	High

		RECEPTORS					
		Residents & Site Users	Construction & Maintenance Operatives	Neighbours	Proposed Building	Aquifer	Watercourse
	Former site use as crash damage repair centre & car wash	_			_		
SOURCES	Hard core & demolition debris within the made ground, asbestos						
Soul	Naturally occurring contaminants						
	Nearby vehicle repair workshop, railway & scrap metal dealer						

2 BRIEF

Mr Michael McQuade of McQuade Property Consultancy Ltd requested a phase 1

environmental desk top study for a site at 219-223 Coldharbour Lane, Brixton,

Lambeth, London, SW9 8RU on behalf of Coldharbour Lane Ltd.

The purpose of this report is to assess the risks to sensitive receptors both on and off-

site due to soil and groundwater contamination as a result of the proposed development. It is based upon information provided by the client, a site visit and walk

and a landon of Control back state of a landon of the state of the sta

over and a Landmark Envirocheck, historical aerial photographs and maps.

A request for information was sent to the local authority however a response had not

been received at time of writing this report.

This report is based upon available factual data for the site obtained only from the

sources described in the text and related to the site on the basis of the location

information provided by the Client. The desk study information is not necessarily

exhaustive and further information relevant to the site may be available from other

sources.

3 SITE VISIT

The site was visited on 19 July 2016. The weather was warm and sunny. Access was

available to all areas of the site and a visual inspection was undertaken. A

photographic record was made during the visit and this is contained in appendix C.

The client's confidentiality was maintained at all times during discussion with third

parties.

0973-P1E-1: 219-223 Coldharbour Lane, Brixton

Coldharbour Lane Ltd

4 SITE LOCATION

The site is situated on the east of the junction of the A2217, Loughborough Rd. and the B222, Hinton Rd. Refer to Figure 1.

The National Grid Reference for the approximate site centre is 531910 175760.





Figure 1: Site Location Plan

5 SITE DESCRIPTION

The site, which occupies 0.07ha, could be described a "L" shaped in plan, with shorter leg fronting onto Coldharbour Lane and the longer, thinner leg fronting onto Hinton Rd. The northwest and southwest boundaries are therefore formed by the back of footpath to Coldharbour Lane and Hinton Rd respectively. The northeast and southeast boundaries immediately abut the neighbouring buildings, at the southern end this is a vehicle repair workshop and at the northern end a building site where only the outer walls of the former building remain.

There is a concrete surfaced access way on the northeast side of the site which terminates in a hammerhead approximately half way along the length of the site. The remainder of the site is entirely occupied by buildings.

The building occupying the northwest part of the site is largely single storey but there is a two storey section at the northern end. The southern building is single storey. Both buildings appear to be of masonry construction with concrete ground floor slabs, which appear to be in good condition and have profiled cement roof sheeting.



Photograph 1: View of the site from the Northwest

6 GROUND CONDITIONS

6.1 Geology

Reference to the geological survey of Great Britain indicates that beneath made

ground, there are no superficial deposits and the area generally is underlain by

bedrock comprising clay and silt described as London Clay Formation.

No infilled, worked or other made ground is recorded in the vicinity of the site.

6.2 Hydrogeology

The Environment Agency maps show the site to be located over unproductive strata in

the bedrock.

While the site is not underlain by a superficial stratum it is within 46m of a superficial

stratum containing a Secondary A Aquifer.

Secondary A Aquifers comprise permeable layers capable of supporting water

supplies at a local rather than strategic scale, and in some cases forming an important

source of base flow to rivers. These are generally aquifers formerly classified as minor

aquifers.

The soil underlying the site is of negligible permeability. The soils overlying the nearby

aquifer are assumed to have a high leaching potential (U) and a worst case

vulnerability classification (H) is assumed due to a lack of data available for urban

areas.

The Environment Agency maps show the site is not located within a source protection

zone of a borehole abstraction point.

The Environment Agency define a zone according to how the groundwater behaves in

that area. From this a model of the groundwater environment is developed on which to

define the zones.

Groundwater source catchments are divided into three zones:

SPZ1 – Inner protection zone

Defined as the 50 day travel time from any point below the water table to the source.

This zone has a minimum radius of 50 metres.

SPZ2 – Outer protection zone

Defined by a 400 day travel time from a point below the water table. This zone has a

minimum radius of 250 or 500 metres around the source, depending on the size of the

abstraction.

SPZ3 – Source catchment protection zone

Defined as the area around a source within which all groundwater recharge is

presumed to be discharged at the source. In confined aquifers, the source catchment

may be displaced some distance from the source. For heavily exploited aguifers, the

final Source Catchment Protection Zone can be defined as the whole aguifer recharge

area where the ratio of groundwater abstraction to aquifer recharge (average recharge

multiplied by outcrop area) is >0.75.

6.3 Hydrology

No water courses or other surface water features of significance have been identified

in the vicinity of the site.

The Environment Agency maps show the site is not located within a flood zone.

The British Geological Society data shows the site does not lie in an area at risk from

groundwater flooding.

Copy of extracts from the Landmark report are contained in appendix D.

6.4 Ground Stability Hazards

No areas of artificial ground, including made ground, worked ground, in-filled ground,

landscaped ground or disturbed ground have been identified either on site or in the

vicinity.

The ground beneath the site has been identified as having a very low risk of potential

ground instability due to collapsible ground, landslide ground and a moderate risk of

potential ground instability due to shrinking or swelling clay. These risks would be

expected to manifest themselves as excessive settlement in the buildings on the site. However, the risks identified are considered unlikely to be of concern to any new buildings, as the foundation design will be based upon geotechnical information obtained from a site-specific intrusive investigation.

6.5 Mining Activities

Reference to the Coal Authority data indicates that the site is not within an area of known coal mining. There is no other known mining in the area.

6.6 Radon Gas

The Landmark Envirocheck Data also advises that the site lies within an area where less than 1% of properties are above the action level and that no protection measures are required in the construction of new properties.

6.7 Sensitive Land Use

Environmentally Sensitive Areas include Nitrate Sensitive Areas, Sites of Special Scientific Interest (SSSI's), Areas of Outstanding Natural Beauty (AONB), National Parks, National Nature Reserves, Special Areas of Conservation, Special Protection Areas and RAMSAR sites. According to the Landmark Envirocheck Data, the Site is not located on or close to any such Environmentally Sensitive Areas.

7 SITE HISTORY

Copies of the Historical Ordnance Survey maps that have been obtained from The Landmark information group are contained in appendix E.

The maps have been reviewed and items of interest and potential sources of contamination, both on the site and within the surrounding area up to 500 metres from the site boundary are noted hereunder.

Site Usage

From	То	Description
1850	1873	Site appears to be open land with the adjacent roads shown.
1873	1903	Some buildings in the north and south east part of site. The

		rest of the site is occupied by what appears to be gardens or
		soft landscape.
1903	1910	Buildings in the north and south east part of site now appear to
		be commercial buildings such as a bakehouse, toy store,
		hardware store and shops. South part of site is labelled as
		scattered timber.
1910	1951	Appears to be buildings developed in the south part of the site.
1951	1955	Building in the north part of site are no longer shown. In the
		west part of site there appears to be a ruin shown and
		buildings are still shown.
1955	1958	Ruin is no longer shown. Appears to be a garage either on or
		adjacent the south east part of site. Scattered timber area in
		the south is now shown as a building.
1958	1974	Only a building is located on the site, on the southern part.
1974	2016	A building has been developed on the west side of the
		property.

Surrounding Area

From	То	Name	Direction	Distance (m)
1873	1896	Nursery	S	34
1873		Rail	Е	6
1873		Rail	S	20
1873		Rail	NW	43
1875	1974	Embankment	S	86
1896	1916	Drill Ground	N	122
1903	1955	Laundry	N	41
1903	1955	Printers	N	59
1903		Timber Stage	NE	27
1910	1951	Mortuary	E	214
1910	1991	Disinfecting Station	E	211
1916	1951	Brigade HQ	N	142
1951		Electric Sub Station	S	68
1951		Works	SE	116
1951		Timber Yard	NE	174
1955	1961	printer	S	56
1955		Garages	SE	3
1955		Garage	N	8
1958	1974	Depot	SE	30
1958	1974	Garage	SE	120
1958	1974	Works	N	182

1958	1991	Depot	S	44
1958		Engineering Works	E	226
1974		Electric Sub Station	SE	16
1974		Industrial Estate	E	25
1974		Engineering Works	N	157
1981		Works	E	123
1987		Industrial Estate	S	205

8 PROPOSED DEVELOPMENT

Plan details for the proposed redevelopment of the site are shown on the Andy Smith Design drawing, P.03 contained in appendix B.

The drawing shows a development comprising retail and some general storage for refuse and cycles at ground floor, offices at first floor and residential above. There are no soft landscaped areas. Pedestrian access to the property is gained via both Hinton Rd. and the access way on the northeast boundary.

Vehicular access is provided from Coldharbour Lane with an access way along the northeast side of the site which terminates in a turning head.

9 POTENTIAL CONTAMINATION

9.1 General

From observations made during the site visit review of the historical maps and the Landmark information, potential sources of on-site contamination and off-site contamination have been identified.

No significant potential sources of contamination have been identified beyond a 250 metre boundary which are considered likely to have any impact on the site. Where there are similar industries and activities in the same direction, only the nearest has been listed.

Copies of the relevant extracts are contained in appendix D.

The legislative framework for the regulation of contaminated land is embodied in Part IIA of the Environmental Protection Act 1990, implemented in the Contaminated Land (England) Regulations 2000. This legislation allows for the identification and remediation of land where contamination is causing unacceptable risks to human health or the wider environment. The approach adopted by UK contaminated land policy is that of "suitability for use" which implies that the land should be suitable for its current use and made suitable for any proposed future use.

In this preliminary contamination assessment the site has been modelled using the Source-Pathway-Receptor approach to produce a site specific conceptual model.

Source - substances or potential contaminants which may cause harm

Pathway - a linkage or route between a source and receptor

Receptor - humans, plant life, groundwater etc., which could be harmed by a contaminant

Geological records indicate that the site is not underlain by an aquifer and therefore there is not considered to be a significant potential for contaminants to be transported either to or from site in the groundwater, however the site is within 46m of an aquifer in the superficial stratum, the aquifer lies downslope from the site and could potentially be affected by run-off from site. There remains the possibility of some limited local transport of contaminants in perched water within made ground overlying the London Clay Formation.

The topography of the area falls gently to the northeast and therefore it is assumed that any movement there might be of perched water trapped in the made ground overlying the London Clay Formation would be to the northeast.

9.2 Off Site Contamination

Description	Direction	Distance (m)
Discharge Consents:		
None identified.	-	-
Local Authority Dellution Provention 9 Controls	7. ** 4 d 4 :	
Local Authority Pollution Prevention & Controls:		
PG6/46 Dry cleaning – 2011 – Permitted	W	47

PG1/1 Waste oil burners – Authorisation revoked	SE	95
PG1/14 Petrol filling station – 2011 Authorised	SE	123
PG3/16 Mobile screening and crushing processes - Authorised	NE	137
Authorised	4	
Category 1 and 2 Pollution Incidents to Controlled Waters:		
None identified.	-	-
Prosecutions Relating to Authorised Processes:		
None identified.	-	-
Substantiated Category 1 and 2 Pollution Incidents:	10 mg	
None identified.	_	
Trong lagritings.		
Control of Major Accident Hazards Sites (COMAH) & Plannin Consents	ng Hazardou	ıs Substance
None identified.	-	-

Landfill and Other Waste Sites:		
Licensed Waste Management Facilities: HCI Waste TS + treatment – 1992 – 2012 - Transferred	SW	108
Licensed Waste Management Facilities: Clinical Waste		400
Transfer Stations – 1993 – Issued	E	188
Licensed Waste Management Facilities: Vehicle Depollution Facility – 2015 – Issued	N	199
Registered Waste Transfer Site: 2000	SW	101
Registered Waste Transfer Site: 1992	SW	101
Registered Waste Transfer Site: 1993	E	204
Registered Waste Treatment or Disposal Sites: Scrapyard – Licence lapsed – 1992	SW	126
Registered Waste Treatment or Disposal Sites:		
Incineration – Recorded Superseded – 1983	SE	139
Historical and Current Land Uses:		
Name: Auto Sistance Location: London, SE24 0HJ Classification: Car Breakdown & Recovery Services		
Status: Active Positional Accuracy: Automatically positioned to the		
address	S	1

Name: Lomac Engineering Co Ltd		
Location: 215-217, Coldharbour Lane, London, SW9 8RU		
Classification: Engineers - General		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	NE	4
Name: City Autos		
Location: 1-5, Hinton Road, London, SE24 0HJ		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Manually positioned to the address or		
location	SE	5
Name: S M R	OL.	J
1 1 2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
Location: 1-5, Hinton Road, London, SE24 0HJ		
Classification: Scrap Metal Merchants		
Status: Active		
Positional Accuracy: Automatically positioned to the	0-	_
address	SE	5
Name: Mr Tipper Ltd		
Location: 7, Hinton Road, London, SE24 0HJ		
Classification: Recycling Centres		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	SE	5
Name: Rapid Recovery		
Location: Unit 6,8,Higgs Ind Est,Herne Hill Rd, London,		
SE24 0AU		
Classification: Car Breakdown & Recovery Services		
Status: Inactive		
Positional Accuracy: Manually positioned to the address or		
location	SE	35
Name: Metal Artefacts	<u> </u>	
Location: 210, Coldharbour Lane, London, SW9 8SA		
Classification: Gate Manufacturers		
Status: Inactive		
Positional Accuracy: Automatically positioned to the address	N	38
	IN	30
Name: Marden Taxi Garage		
Location: 4-6 Rathgar Rd, London, SW9 7EL		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Manually positioned to the road within		
the address or location	NW	45
Name: Super Dry Cleaners		
Location: 228, Coldharbour Lane, London, SW9 8SD		
Classification: Dry Cleaners		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	W	47
Name: Brixton Auto Centre Ltd		
Location: Arch 498-499,Ridgeway Road, London, SW9	W	55

[·		
7EX		
Classification: Garage Mechanics		
Status: Active		
Positional Accuracy: Manually positioned to the address or		
location		
Name: Phoenix Forge		
Location: 453 Rathgar Rd, London, SW9 7EP		
Classification: Blacksmiths & Forgemasters		
Status: Inactive		
Positional Accuracy: Manually positioned to the road within		
the address or location	N	57
Name: Mayflower Mg & Vw Services Ltd		
Location: 20-28, Hinton Road, London, SE24 0HJ		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	S	58
Name: King Of Garments		
Location: Shakespeare Business Centre, 245a,		
Coldharbour Lane, London, SW9 8RR		
Classification: Dry Cleaners		
Status: Inactive		
Positional Accuracy: Manually positioned to the address or		
location	S	73
Name: First Western Corporation		
Location: Shakespeare Business Centre 245a,		
Coldharbour Lane, London, SW9 8RR		
Classification: Recycling Services		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	S	73
Name: Green Oil		
Location: Unit 202, Shakespeare Business Centre, 245a,		
Coldharbour Lane, London, SW9 8RR		
Classification: Lubricant Manufacturers & Distributors		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	S	73
Name: Auto Care	_	. •
Location: Arch 496a, Rathgar Road, London, SW9 7EP		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	N	79
Name: Deans Car Care	1.4	, , ,
Location: 505, Arches, Ridgeway Road, London, SW9 7EX		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	W	88
Name: Paramount London Ltd	SW	89

Location: Arch 15-25, Belinda Road, London, SW9 7DT		
Classification: Scrap Metal Merchants		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address		
Name: Euroride Cars		
Location: 519 Belinda Rd, London, SW9 7DT		
Classification: Car Dealers		
Status: Inactive		
Positional Accuracy: Manually positioned to the road within		
the address or location	SW	91
Name: Portslade Garage Services	Ovv	J 1
Location: 1, Herne Hill Road, London, SE24 0AU		
Classification: Garage Services		
Status: Inactive		
Positional Accuracy: Manually positioned to the address or		00
location	NE	92
Name: Robson & Francis Rewinds		
Location: Unit 2, Hardess Street, London, SE24 0HN		
Classification: Electric Motor Sales & Service		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	SE	93
Name: K & S Engineering Ltd		
Location: Unit 1, Hardess Street, LONDON, SE24 0HN		
Classification: Engineers - General		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	SE	93
Name: Brixton Engine Centre	<u> </u>	- 00
Location: Belinda Rd, London, SW9 7DT		
Classification: Engines - Sales & Service		
Status: Inactive		
Positional Accuracy: Manually positioned to the road within	0)4/	00
the address or location	SW	96
Name: Austin'S Garage		
Location: Railway Arch, 254-255, Hardess Street, London,		
SE24 0HN		
Classification: Garage Services		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	Е	102
Name: Herne Hill Service Station		
Location: 42, Hinton Road, London, SE24 0HJ		
Classification: Petrol Filling Stations		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	SE	123
Name: 2 Ms Auto Repairs	- -	
Location: 511, Arches, Ridgeway Road, London, SW9 7EX		
Classification: Mechanical Engineers	SW	125
Olassinoation, Mostariloai Enginocis		120

Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address		
Name: Personal Print		
Location: 5-9, Herne Hill Road, London, SE24 0AU		
Classification: Printers		
Status: Inactive		
Positional Accuracy: Manually positioned to the address or		
location	Е	126
Name: J Connolly & Sons		
Location: 2-22, Padfield Road, London, SE5 9AA		
Classification: Waste Disposal Services		
Status: Active		
Positional Accuracy: Automatically positioned to the		
address	NE	126
Name: A-Z Services		
Location: 194, Coldharbour Lane, London, SE5 9QH		
Classification: Printers		
Status: Inactive		
Positional Accuracy: Automatically positioned to the		
address	NE	133
Artificial Ground and Made Ground:		
None identified.	-	-

There are a large number of commercial enterprises in the vicinity that are potential sources of contamination.

As the area slopes down to the northwest and as there is no underlying aquifer with only the potential for contaminants to be transported in any perched water only those potential sources to the south and east in close proximity have been considered as likely to impact the site.

Potential sources of contamination identified and considered potentially to significantly impact the site are the vehicle repair workshop immediately south and the railway. A scrap metal dealer is listed as being immediately south of the site, at the premises currently occupied by the above noted vehicle repair workshop, and is assumed to have predated the current occupant.

9.3 On Site Contamination

No olfactory or visual evidence of contamination was noted on site. There remains however the potential contamination of the site from its former uses, which include a

car wash and as a crash repair centre.

Some redevelopment of the site has occurred and there is the potential for demolition debris to remain buried on site, also for contaminants to be contained in any hard core or other fill below existing ground slabs.


Due to the lack of any major redevelopment of the area historically it is considered unlikely that there is a significant depth of fill material beneath the site, and therefore there is not considered to be an on-site source of ground gas.

Southwark was subjected to bombing runs during World War II, and records of high explosive bombs have been identified in the surrounding area on The Bomb Sight project web-mapping tool. No records have been identified on-site, and it is considered unlikely that any unexploded ordnance would be present, however caution should be taken when excavating site ground for any unexpected items.

9.4 Preliminary Conceptual Model

		POTENTIAL PATHWAYS													
		Inhalation of contaminated vapour	Inhalation of contaminated dust	Direct Soil Ingestion	Direct dermal contact	nhalation of asbestos	Drinking contaminated water supply	Direct contact of soil with building materials	Surface water run-off	Surface water percolation to groundwater	Migration via groundwater	Build-up of ground gas		0111777	
		Inha	Inha	Dire	Dire	Inha	Drin wate	Dire build	Surf	Surf to gr	Migr grou	Builc	COMMENTS ON DISCOUNTED PATHWAYS		
	Site Users / Residents	Υ	N	N	N	N	Υ					N	No soft landscape and permeable areas are proposed, therefore these pathways will not be created.	No potentially significant sources of land gas identified.	
ORS	Construction / Maintenance Operatives	Y	Υ	Υ	Υ	Υ						N		This is to be reviewed if significant	
RECEPTORS	Neighbours	Υ	Υ			Υ			Υ		Υ	N		organic containing	
REC	Proposed Building							Υ				N		material is identified on site.	
	Watercourse								N		N		None identified		
	Aquifer									N			Given that the proposed building covers the site footprint the potential for run-off is considered negligible		

Schematic Conceptual Model



10 RISK ASSESSMENT

The level of information provided by the Landmark report and historic Ordnance Survey maps, together with the other information within the report is considered suitable to provide the data for a satisfactory risk assessment for the site. While there will always be uncertainties due to known or unknown gaps in information it is considered that sufficient information is available to reduce those uncertainties to within acceptable limits for the nature of the site under review.

An asbestos survey of existing structures and infrastructure (as defined under Section 5(a) of the Control of Asbestos Regulations 2012) was beyond the brief of this report. The risk assessment has been undertaken on the basis that should asbestos be identified within buildings or infrastructure, these materials will be removed appropriately by licensed contractors and asbestos materials disposed of in accordance with legal requirements prior to demolition or other works in order to avoid contaminating soils at the site.

SOURCES	POTENTIAL POLLUTANT	RECEPTOR	PATHWAY	HAZARD SEVERITY	LIKELIHOOD OF OCCURRENCE	RISK/ SIGNIFICANCE	COMMENT & CONTROL MEASURES
Former site use as crash damage	Metals Hydrocarbons	Residents &	Inhalation of vapours, indoors and outdoors	Medium	Low likelihood	Moderate/Low risk	Contamination testing across site & remediation if required
repair centre & car wash	=	Site Users	Drinking of water from supply impacted by contaminated soil	Medium	Likely	Moderate risk	Upgraded water supply pipe may be required by water supply company. It is recommended that this report is provided to the water supplier with a request for the testing, if any, that they require.

SOURCES	POTENTIAL POLLUTANT	RECEPTOR	PATHWAY	HAZARD SEVERITY	LIKELIHOOD OF OCCURRENCE	RISK/ SIGNIFICANCE	COMMENT & CONTROL MEASURES
			Dermal contact	Mild	High likelihood	Moderate risk	-Information to be
Former site use as crash Metals	Construction operatives	Inhalation of vapours, indoors and outdoors	Mild	Low likelihood	Low risk	contained in site Health & Safety Plan. Use of appropriate ppe and normal good hygiene	
			Soil Ingestion	Medium	Likely	Moderate risk	measures. Appropriate dust control measures during construction. Information to be contained in site Health & Safety Plan. Services to be laid in clean imported fill.
			Inhalation of contaminated dust	Mild	High likelihood	Moderate risk	
damage repair centre & car wash	Hydrocarbons PAHs	Maintenance Operatives	Dermal contact	Mild	High likelihood	Moderate risk	
& Cal Wasii			Inhalation of vapours, indoors and outdoors	Mild	Low likelihood	Low risk	
			Soil Ingestion	Medium	Likely	Moderate risk	
			Inhalation of contaminated dust	Mild	Likely	Moderate/Low risk	

SOURCES	POTENTIAL POLLUTANT	RECEPTOR	PATHWAY	HAZARD SEVERITY	LIKELIHOOD OF OCCURRENCE	RISK/ SIGNIFICANCE	COMMENT & CONTROL MEASURES
			Inhalation of vapours, indoors and outdoors	Minor	Unlikely	Very low risk	No action required
Former site use as crash damage	Metals Hydrocarbons	Neighbours	Inhalation of contaminated dust	Mild	Likely	Moderate/Low risk	Appropriate dust control measures during construction. No soft landscaping in completed scheme.
repair centre & car wash		Lateral migration of perched water	Medium	Unlikely	Low risk	No residential gardens in close proximity down	
			Surface water run-off	Medium	Unlikely	Low risk	gradient, no action required.

SOURCES	POTENTIAL POLLUTANT	RECEPTOR	PATHWAY	HAZARD SEVERITY	LIKELIHOOD OF OCCURRENCE	RISK/ SIGNIFICANCE	COMMENT & CONTROL MEASURES
Former site use as crash damage repair centre & car wash	Sulphates	Proposed Building	Direct contact of soil with building materials	Medium	Likely	Moderate Risk	It is recommended that an appropriate intrusive geotechnical site investigation is undertaken in order to allow the most suitable foundations to be designed.
		Neighbours		Severe	Unlikely	Moderate/Low risk	Dust control during construction. Any debris from earlier demolition found during site strip is to
Hard core & demolition debris within the made ground	Asbestos	Construction operatives	Inhalation	Severe	Low likelihood	Moderate risk	be inspected for asbestos by a suitably experienced contractor.
ground		Maintenance Operatives		Severe	Unlikely	Moderate/Low risk	Information to be contained in site Health & Safety Plan. Services to be laid in clean imported fill.

SOURCES	POTENTIAL POLLUTANT	RECEPTOR	PATHWAY	HAZARD SEVERITY	LIKELIHOOD OF OCCURRENCE	RISK/ SIGNIFICANCE	COMMENT & CONTROL MEASURES
Naturally occurring contaminants	Sulphates pH	Proposed Building	Direct contact of soil with building materials	Medium	Likely	Moderate Risk	It is recommended that an appropriate intrusive geotechnical site investigation is undertaken in order to allow the most suitable foundations to be designed.
Vahiala		Residents & Site Users	Lateral	Mild	Low likelihood	Low risk	No action required
Vehicle repair workshop, railway & scrap metal dealer	Hydrocarbons PCB's	Construction & Maintenance Operatives	migration of perched water transporting contaminants to site	Mild	Likely	Moderate/Low risk	Information to be in site Health & Safety Plan. Use of appropriate ppe and normal good hygiene measures. Appropriate dust control during construction.

Any visual or olfactory evidence of contamination noted during works should be investigated by a suitably qualified person and their recommendations implemented.

11 SITE WORK

11.1 Investigations

11.1.1 In order to determine if either the former usage of the property or off-site sources are a potential cause of contamination it is considered prudent that some site investigation should be undertaken based upon the requirements of BS 10175: 2001 which is the code of practice for the investigation of potentially contaminated sites. This may need to be phased with a preliminary investigation to determine if any further, or more detailed investigation is required. It is proposed that soil samples be taken from representative locations around the site and tested for a typical range of determinands, comprising asbestos, heavy metals, pH, speciated aromatic and aliphatic hydrocarbons and speciated PAHs.

11.1.2 It is considered unlikely, however if significant organic containing material is identified within the made ground, then monitoring of potential ground gases, over a suitable period of time, may be required in order to determine the requirement for gas mitigation measures. Information to be contained in site Health & Safety Plan.

11.2 Site Preparation

During the works a watching brief should be maintained by an experienced person. Should any visual or olfactory evidence of contamination be noted during the works GO Contaminated Solution Ltd and the local authority Environmental Health Officer (EHO) should be contacted. GO Contaminated Solution Ltd shall assess if further intrusive investigation and remediation is required. Proposals will be issued to the EHO for comment prior to undertaking the additional investigation or implementing the remediation strategy.

The form of investigation proposed in 11.1.1 will indicate if there is any contamination present and if it is necessary will enable remedial works to be formulated.

If any potentially contaminated spoil is to be removed from site, the Waste Acceptance Criteria (WAC) testing should be agreed with the facility to which the spoil is being transported. It is recommended that consideration is given to this testing as part of the phase 2 investigation. Guidance can be obtained from Environment Agency document

Waste Sampling and Testing for Disposal to Landfill.

11.3 External Works

In regard to water supply reference should be made to the UK Water Industry

Research (UKWIR) publication "Guidance for the Selection of Water Supply Pipes to

be used in Brownfield Sites" (Ref 10/WM/03/21; the 'UKWIR Guidance'). This

document provides guidance to ensure that water quality is safeguarded by identifying suitable pipe materials and components to be used below ground in potentially

contaminated sites. An upgraded water supply pipe may be required by the water

supply company. It is recommended that this report is provided to the water supplier

with a request for the testing, if any, that they require.

12 SITE DEVELOPMENT CONSIDERATIONS

During the course of the site visit and preparation of this report the following items,

whilst not within the scope of this report, have come to our attention and should be

considered. This is not necessarily an exhaustive list.

12.1 An intrusive geotechnical investigation may be required to provide detailed

information about the engineering nature of the ground, in order to allow the

most suitable foundations in terms of economy and performance to be

designed. This should follow the recommendations of BS 5930, the Code of

Practice for site investigations with tests carried out to satisfy the requirements of BS 1377, the Code of Practice for methods of tests for soils for civil

engineering purposes. It is recommended that this includes testing for

sulphates.

12.2 As redevelopment of the property is proposed it is recommended that a full

topographical survey is undertaken, if one is not available. This should identify

all relevant features, boundaries and levels relating to the site and should also

include ground levels on the adjacent properties and roads.

12.3 If it is proposed to make use of the existing drainage system, or any existing

connections to the mains sewers. A CCTV survey should be considered in order to determine both the general condition and suitability for the proposed use.

12.4 If any excavation works are proposed, it is recommended that all the relevant

utility companies are contacted to ascertain what pipes, cables, wires, lines and

other apparatus exist close to where the work is to take place.

12.5 An asbestos survey of existing structures and infrastructure (as defined under

Section 5(a) of the Control of Asbestos Regulations 2012) was beyond the brief of this report. Advice should be sought regarding the potential presence and

management of asbestos within existing structures and infrastructure.

13 CONCLUSIONS

Based upon the information currently available, there would in principle, appear to be

no major contamination issues associated with the site, however, the following should

be considered at this stage. It is considered that provided the recommendations of this

report are implemented there is no increased risk to human health from

redevelopment of the site for the proposed mixed retail, office and residential use.

13.1 There is potential contamination of the site from previous redevelopment of the

site, its former use as a crash damage repair centre & car wash and also from

the nearby vehicle repair workshop, railway & scrap metal dealer.

13.2 It is recommended that some preliminary intrusive environmental site

investigation is undertaken to determine if contamination is present on the

property.

13.4 If significant organic containing material is identified within the made ground,

then monitoring of potential ground gases, over a suitable period of time, may

be required in order to determine the requirement for gas mitigation measures.

Information to be contained in site Health & Safety Plan.

13.5 An upgraded water supply pipe may be required by the water supply company.

It is recommended that this report is provided to the water supplier with a

request for the testing, if any, that they require.

13.9 Should any visual or olfactory evidence of contamination be noted during the

works this should be investigated by a suitably qualified person and their


recommendations implemented.

13.10 If any potentially contaminated spoil is to be removed from site, the Waste


Acceptance Criteria (WAC) testing should be agreed with the facility to which the spoil is being transported.

This document has been prepared for the titled project and should not be relied upon or used for any other project without an independent check being carried out as to its suitability and the prior written authority of GO Contaminated Land Solutions Ltd being obtained. No responsibility or liability is accepted for the consequences of this document being used for a purpose other than that for which it was commissioned. Any person using or relying on this document for such other purpose will by such use or reliance be taken to confirm his agreement to indemnify GO Contaminated Land Solutions Ltd for all loss or damage resulting therefrom. GO Contaminated Land Solutions Ltd accepts no responsibility or liability for this document to any party other than Coldharbour lane Ltd by whom it was commissioned.

Appendix A – Site Location Plan



Appendix B – Proposed Site Plan



Appendix C – Photographs



View Looking East towards Site



View Looking southeast from junction along Hinton Rd.



View Looking southwest from junction along Coldharbour Lane



View Looking Northwest from site along Loughborough Rd



View Looking Northeast from site along Coldharbour Lane



View Looking South from Coldharbour Lane of railway east of site



View Looking South of Access Way onto Site



View of site Looking North from Hinton Rd



View of site Access Looking Southeast



View of site Access Looking Northwest



View Looking Southwest from Turning Head towards Building



View Northeast from Building towards Turning Head



Internal view of Northern Building



Internal view of Northern Building





Internal view of Southern Building

Internal view of Southern Building



Roofscape Looking Southeast from first floor



Appendix D – Landmark Report Extra	acts
	lata has been found the relevant detail report sections ave been omitted.



Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Agency & Hydrological					
BGS Groundwater Flooding Susceptibility	pg 1	S	Yes		n/a
Contaminated Land Register Entries and Notices					
Discharge Consents	pg 1				2
Prosecutions Relating to Controlled Waters			n/a	n/a	n/a
Enforcement and Prohibition Notices		5.			
Integrated Pollution Controls		×			
Integrated Pollution Prevention And Control					
Local Authority Integrated Pollution Prevention And Control					
Local Authority Pollution Prevention and Controls	pg 1	9.	4		15
Local Authority Pollution Prevention and Control Enforcements					
Nearest Surface Water Feature	pg 4				Yes
Pollution Incidents to Controlled Waters					
Prosecutions Relating to Authorised Processes	(6	2.		3	
Registered Radioactive Substances	pg 4				14
River Quality					
River Quality Biology Sampling Points	(*	2	7	
River Quality Chemistry Sampling Points					
Substantiated Pollution Incident Register					
Water Abstractions	pg 6	5.		8	1 (*17)
Water Industry Act Referrals					
Groundwater Vulnerability	pg 10	Yes	n/a	n/a	n/a
Drift Deposits			n/a	n/a	n/a
Bedrock Aquifer Designations	pg 11	Yes	n/a	n/a	n/a
Superficial Aquifer Designations			n/a	n/a	n/a
Source Protection Zones	pg 11				1
Extreme Flooding from Rivers or Sea without Defences		8:		n/a	n/a
Flooding from Rivers or Sea without Defences				n/a	n/a
Areas Benefiting from Flood Defences				n/a	n/a
Flood Water Storage Areas		8:		n/a	n/a
Flood Defences				n/a	n/a
Detailed River Network Lines					n/a
Detailed River Network Offline Drainage					n/a

GO Contaminated Land Solutions Ltd



Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Waste					
BGS Recorded Landfill Sites					
Historical Landfill Sites			A.		
Integrated Pollution Control Registered Waste Sites					
Licensed Waste Management Facilities (Landfill Boundaries)					
Licensed Waste Management Facilities (Locations)	pg 12		3	1	4
Local Authority Landfill Coverage		1	n/a	n/a	n/a
Local Authority Recorded Landfill Sites					
Potentially Infilled Land (Non-Water)			Ş.		
Potentially Infilled Land (Water)					
Registered Landfill Sites					
Registered Waste Transfer Sites	pg 14		3	2	3
Registered Waste Treatment or Disposal Sites	pg 17		2		2
Hazardous Substances					
Control of Major Accident Hazards Sites (COMAH)			3		
Explosive Sites			ů.		
Notification of Installations Handling Hazardous Substances (NIHHS)	Ì				
Planning Hazardous Substance Consents					
Planning Hazardous Substance Enforcements			×		



Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m
Geological Geological					
BGS 1:625,000 Solid Geology	pg 19	Yes	n/a	n/a	n/a
BGS Estimated Soil Chemistry					
BGS Recorded Mineral Sites					
BGS Urban Soil Chemistry	pg 19		Yes	Yes	Yes
BGS Urban Soil Chemistry Averages	pg 22	Yes			
Brine Compensation Area			n/a	n/a	n/a
Coal Mining Affected Areas			n/a	n/a	n/a
Mining Instability			n/a	n/a	n/a
Man-Made Mining Cavities			00		
Natural Cavities					
Non Coal Mining Areas of Great Britain				n/a	n/a
Potential for Collapsible Ground Stability Hazards	pg 22	Yes		n/a	n/a
Potential for Compressible Ground Stability Hazards			8	n/a	n/a
Potential for Ground Dissolution Stability Hazards			Ĭ	n/a	n/a
Potential for Landslide Ground Stability Hazards	pg 22	Yes		n/a	n/a
Potential for Running Sand Ground Stability Hazards	pg 22		Yes	n/a	n/a
Potential for Shrinking or Swelling Clay Ground Stability Hazards	pg 22	Yes	<u> </u>	n/a	n/a
Radon Potential - Radon Affected Areas			n/a	n/a	n/a
Radon Potential - Radon Protection Measures			n/a	n/a	n/a
Industrial Land Use					
Contemporary Trade Directory Entries	pg 23		77	62	222
Fuel Station Entries	pg 54		1	3	5
Points of Interest - Commercial Services	pg 54		58	42	34
Points of Interest - Education and Health	pg 65				6
Points of Interest - Manufacturing and Production	pg 66		8	8	17
Points of Interest - Public Infrastructure	pg 69		8	Ĭ	26
Points of Interest - Recreational and Environmental	pg 71		6	14	37
Gas Pipelines	3				
Underground Electrical Cables	pg 76		*		24



Data Type	Page Number	On Site	0 to 250m	251 to 500m	501 to 1000m (*up to 2000m)
Sensitive Land Use					
Ancient Woodland					
Areas of Adopted Green Belt					
Areas of Unadopted Green Belt				1	
Areas of Outstanding Natural Beauty			Č.		
Environmentally Sensitive Areas					
Forest Parks			0	30	
Local Nature Reserves					
Marine Nature Reserves					
National Nature Reserves			Ů		
National Parks			S.		
Nitrate Sensitive Areas					
Nitrate Vulnerable Zones					
Ramsar Sites				30	
Sites of Special Scientific Interest					
Special Areas of Conservation					
Special Protection Areas					
World Heritage Sites					



Agency & Hydrological

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Groundwater I	Flooding Susceptibility			φ.	8
	Flooding Type:	Potential for Groundwater Flooding to Occur at Surface	A13NW (W)	40	2	531850 175765
1	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water. Status: Positional Accuracy:	Kings College London Education Maurice Wohl Neuroscience Institute Cutcombe Road London Se5 9rx Environment Agency, Thames Region Thames Eprsp3727rxm 1 25th May 2012 25th May 2012 Not Supplied Trade Discharges - Cooling Water Into Land Groundwater New issued under EPR 2010 Located by supplier to within 10m	A19SW (NE)	587	3	532327 176194
1	Discharge Consent Operator: Property Type: Location: Authority: Catchment Area: Reference: Permit Version: Effective Date: Issued Date: Revocation Date: Discharge Type: Discharge Environment: Receiving Water: Status: Positional Accuracy:	Kings College London Education Maurice Wohl Neuroscience Institute Cutcombe Road, ., ., London, Se5 9rx Environment Agency, Southern Region Not Supplied Eprsp3727xm 1 25th May 2012 25th May 2012 Not Supplied Trade Discharges - Cooling Water Into Land Groundwater New issued under EPR 2010 Located by supplier to within 10m	A19SW (NE)	587	3	532327 176194
2	Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls Super Dry Cleaning 228 Coldharbour Lane, London, Sw9 8sd London Borough of Lambeth, Environmental Health Department LAPPC/CS/DC 44 14th November 2011 Local Authority Pollution Prevention and Control PG6/46 Dry cleaning Permitted Manually positioned to the address or location	A13NW (W)	47	4	531844 175782
3	Local Authority Pol Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls Emerald Cams Ltd Unit 2, Hardness Street, LONDON, SE24 0HN London Borough of Lambeth, Environmental Health Department 11 Not Supplied Local Authority Air Pollution Control PG1/I/Waste oil burners, less than 0.4MW net rated thermal input Authorisation revokedRevoked Manually positioned to the road within the address or location	A13SE (SE)	95	4	532006 175707
4	Local Authority Pol Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls Save Service Station 42-52 Hinton Road, LONDON, SE24 0HJ London Borough of Lambeth, Environmental Health Department	A13SE (SE)	123	4	531975 175633
5	Local Authority Pol Name: Location: Authority: Permit Reference: Dated: Process Type: Description: Status:	lution Prevention and Controls Primagrange Ltd 2-22 Padfield Road, LONDON, SE5 London Borough of Lambeth, Environmental Health Department 39 Not Supplied Local Authority Air Pollution Control PG3/16 Mobile screening and crushing processes Authorised Manually positioned to the road within the address or location	A13NE (NE)	137	4	532041 175834



Agency & Hydrological

Map ID	Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Drift Deposits None				
	Bedrock Aquifer Designations Aquifer Designation: Unproductive Strata	A13NE (N)	0	2	531907 175765
	Superficial Aquifer Designations No Data Available				
25	Source Protection Zones Name: Brixton Source: Environment Agency, Head Office Th408 Type: Zone II (Outer Protection Zone): Either 25% of the source area or a 400 day travel time whichever is greater.	A7SE (SW)	812	3	531514 175032
	Extreme Flooding from Rivers or Sea without Defences None				
	Flooding from Rivers or Sea without Defences None				
	Areas Benefiting from Flood Defences None			»	
	Flood Water Storage Areas None				2
	Flood Defences None			8-	
	Detailed River Network Lines None			8	
	Detailed River Network Offline Drainage None				



Waste

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR	
	Licensed Waste Ma	nagement Facilities (Locations)				-	
26	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference:	83255 4-16 & 1-3 Belinda Road , Brixton, London, SW9 7DT Powerday Plc Not Supplied Environment Agency - South East Region, Kent & South London Area HCI Waste TS + treatment Transferred 21st July 1992 26th June 2012 Not Supplied Located by supplier to within 10m	A13SW (SW)	108	3	531810 175697	
	Licensed Waste Ma	nagement Facilities (Locations)	T i				
27	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	83254 26 Wanless Road , London, SE24 0HW Lambeth London Borough Council Not Supplied Environment Agency - South East Region, Kent & South London Area Clinical Waste Transfer Stations Issued 19th May 1993 Not Supplied Located by supplier to within 10m	A13SE (E)	188	3	532105 175728	
	Licensed Waste Ma	nagement Facilities (Locations)					
28	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	402128 Plot 1, Gordon Grove, Camberwell, Greater London, SE5 9DW Vauxhall Mania Limited Not Supplied Environment Agency - South East Region, Kent & South London Area Vehicle Depollution Facility <5000 tps Issued 22nd January 2015 Not Supplied Located by supplier to within 10m	A13NW (N)	199	3	531885 175988	
	Licensed Waste Ma	nagement Facilities (Locations)	7		×		
29	Licence Number: Location: Operator Name: Operator Location: Authority: Site Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	102085 Arch 439, Gordon Grove, Camberwell, London, SE5 9DW Golden Motor Care Ltd Not Supplied Environment Agency - South East Region, Kent & South London Area Vehicle Depollution Facility <5000 tps Modified 23rd November 2010 4th August 2015 Not Supplied	A13NE (N)	310	3	531910 176100	
		nagement Facilities (Locations)					
30	Licence Number: Location: Operator Name: Operator Location: Authority: Sife Category: Licence Status: Issued: Last Modified: Expires: Suspended: Revoked: Surrendered: IPPC Reference: Positional Accuracy:	83291 Valentia Place, Coldharbour Lane, Brixton, London, SW9 J E Doorey Metal Co Ltd Not Supplied Environment Agency - South East Region, Kent & South London Area Metal Recycling Sites (Mixed) Surrendered 2nd November 1993 Not Supplied St December 1998 Not Supplied Located by supplier to within 10m	A12SE (SW)	577	3	531392 175480	



Waste

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Registered Waste T	ransfer Sites				7)
34	Licence Holder: Licence Reference: Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	Tenmead Ltd DL396 4-16 Belinda Road, LAMBETH, London, SW9 7DT 2 Royal Terrace, SOUTHEND ON SEA, Essex, SS1 1EB Environment Agency - Thames Region, South East Area Transfer Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) No known restriction on source of waste Operational as far as is knownOperational 25th May 2000 DL396 Not Given Manually positioned to the address or location Not Supplied Degradable Household/Commercial/Industrial Waste - But With Inert Materials (As In Post'98 E.A.Lics And Equivalent To 21.00.00) Maximim Putrescible Waste Limited To	A13SW (SW)	101	3	531820 175695
	Prohibited Waste	Maximum Waste Permitted By Licence Clinical - As In Control.Led Waste Regs 1992 Metal Waste/Scrap Metal (As In Post'98 E.A.Lics And Equivalent To 23.00.00) Other Waste/Waste Not Otherwise Specified Special Waste (As In Epa 1990:S62 Of 1996 Regs)				
	Registered Waste T	ransfer Sites				0
34	Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	Tenmead Ltd DL396 4-16 Belinda Road, LAMBETH, London, SW9 7DT 2 Royal Terrace, SOUTHEND ON SEA, Essex, SS1 1EB Environment Agency - Thames Region, South East Area Transfer Medium (Equal to or greater than 25,000 and less than 75,000 tonnes per year) No known restriction on source of waste Record supersededSuperseded 21st July 1992 Not Given DL396 Manually positioned to the address or location Not Supplied Lwra Cat. A = Inert Wastes Lwra Cat. Bi Gen. Non-Putresc Max. Waste Permitted By Licence-Stated Clinical - As In Coll/Disp.Regs Of '88 Liquid/Sludge Wastes Poisonous, Noxious, Polluting Wastes Shotblast Res/Silicate Slag/Boil.Scale Special Wastes	A13SW (SW)	101	3	531820 175695
-	Registered Waste T	ransfer Sites	- 3		Ç	Ř.
35	Licence Holder: Licence Reference: Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence: Positional Accuracy: Boundary Quality: Authorised Waste	Environmental Services Unit, Wanless Road, LAMBETH, London, SE24 0HW Town Hall, Catford, LEWISHAM, London, SE6 4RU Environment Agency - Thames Region, South East Area Transfer Very Small (Less than 10,000 tonnes per year) No known restriction on source of waste Operational as far as is knownOperational 19th May 1993 DL112 Not Given Manually positioned to the address or location Not Supplied Clinical - As In Coll/Disp.Regs Of '88 Liq. Pharmaceutical Products	A13SE (E)	204	3	532120 175715
	Boundary Quality:	Not Supplied Clinical - As In Coll/Disp.Regs Of '88				



Waste

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Registered Waste T	reatment or Disposal Sites				6
39	Licence Holder: Licence Reference: Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	D A & P D Warner t/a Paramount Metal Co Ltd DL371 1-35 Belinda Road, LAMBETH, London, SW9 7DT	A13SW (SW)	126	3	531800 175680
40	Licence Holder: Licence Reference: Site Location: Operator Location: Authority: Site Category: Max Input Rate: Waste Source Restrictions: Licence Status: Dated: Preceded By Licence: Superseded By Licence:	Treatment or Disposal Sites L.B. of Lambeth DL112 Wanless Road, LAMBETH, London, SE24 138/146 Clapham Road, LAMBETH, London, SW4 7DD Environment Agency - Thames Region, South East Area Incineration Very Small (Less than 10,000 tonnes per year) No known restriction on source of waste Record supersededSuperseded 1st March 1983 Not Given DL112 Manually positioned to the road within the address or location Not Supplied Clinical Wastes Notifiable Wastes Special Wastes	A13SE (SE)	139	3	532050 175700



Geological

Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	BGS Urban Soil Che	emistry Averages			*	
	Source: Sample Area: Count Id:	British Geological Survey, National Geoscience Information Service London 7209	A13NE (N)	0	2	531907 175765
	Arsenic Minimum Concentration: Arsenic Average	1.00 mg/kg				
	Concentration: Arsenic Maximum	17.00 mg/kg 161.00 mg/kg				
	Concentration: Cadmium Minimum	SELECTION CONTROL CONT				
	Concentration: Cadmium Average	0.90 mg/kg				
	Concentration: Cadmium Maximum	to Made and the Common and the Commo				
	Concentration: Chromium Minimum	13.00 mg/kg				
	Concentration: Chromium Average	79.00 mg/kg				
	Concentration: Chromium Maximum	2094.00 mg/kg				
	Concentration: Lead Minimum	11.00 mg/kg				
	Concentration: Lead Average	280.00 mg/kg				
	Concentration: Lead Maximum	10000.00 mg/kg				
	Concentration: Nickel Minimum	2.00 mg/kg				
	Concentration: Nickel Average	28.00 mg/kg				
	Concentration: Nickel Maximum Concentration:	506.00 mg/kg				
	Coal Mining Affecte	d Areas not be affected by coal mining	8		/ //	
	Service and the service and th	eas of Great Britain				
	Potential for Collap	sible Ground Stability Hazards	K		**************************************	
	Hazard Potential: Source:	Very Low British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
	Potential for Compr Hazard Potential: Source:	essible Ground Stability Hazards No Hazard British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
	Potential for Ground Hazard Potential: Source:	d Dissolution Stability Hazards No Hazard British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
		ide Ground Stability Hazards	6.7	9		11172.78
	Hazard Potential: Source:	Very Low British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
		ng Sand Ground Stability Hazards				
	Hazard Potential: Source:	No Hazard British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
		ng Sand Ground Stability Hazards	Adobbas	40		E24052
	Hazard Potential: Source:	Very Low British Geological Survey, National Geoscience Information Service	A13NW (NW)	46	2	531852 175803
	Potential for Shrink Hazard Potential:	ing or Swelling Clay Ground Stability Hazards Moderate	A13NE	0	2	531907
	Source:	British Geological Survey, National Geoscience Information Service	(N)	U	85	175765
	Potential for Shrink Hazard Potential: Source:	ing or Swelling Clay Ground Stability Hazards No Hazard British Geological Survey, National Geoscience Information Service	A13NW	124	2	531787 175843
	Control Section Section Section 1	adon Affected Areas	(NW)		· · · · · · · · ·	113043
	Affected Area:	The property is in a lower probability radon area, as less than 1% of homes are above the action level British Geological Survey, National Geoscience Information Service	A13NE (N)	0	2	531907 175765
	The second secon	adon Protection Measures			12	
	Protection Measure:	No radon protective measures are necessary in the construction of new dwellings or extensions	A13NE (N)	0	2	531907 175765



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
43	Location: Lo Classification: Ca Status: Ad	irrectory Entries ito Sistance indon, SE24 0HJ ar Breakdown & Recovery Services tive itomatically positioned to the address	A13SE (S)	1	3	531908 175757
43	Location: 1, Classification: Ca Status: Ac	irectory Entries to Assistance Ltd Hinton Road, London, SE24 0HJ ar Breakdown & Recovery Services tive itomatically positioned to the address	A13SE (S)	1	89	531908 175757
43	Location: 7, Classification: Re Status: Ind	irectory Entries Tipper Ltd Hinton Road, London, SE24 0HJ scycling Services active Itomatically positioned to the address	A13SE (SE)	5	13	531920 175747
43	Location: 7, Classification: Re Status: Ind	irectory Entries Tipper Ltd Hinton Road, London, SE24 0HJ scycling Centres active Itomatically positioned to the address	A13SE (SE)	5	ž.	531920 175747
43	Location: 7, Classification: Sc Status: Ind	irectory Entries aples Recyclers Hinton Road, London, SE24 0HJ rap Metal Merchants active itomatically positioned to the address	A13SE (SE)	5	*	531920 175747
43	Location: 1-5 Classification: Sc Status: Ac	irrectory Entries M.R. 5, Hinton Road, London, SE24 0HJ rap Metal Merchants ctive utomatically positioned to the address	A13SE (SE)	5	8	531920 175747
43	Contemporary Trade D Name: Cit Location: 1-5 Classification: Gas Status: Ind	DVIDSLESS SERVICE SERV	A13SE (SE)	5	5	531920 175747
43	Contemporary Trade D Name: Cit Location: 1-5 Classification: Mo Status: Inc.	ACTION OF THE CONTRACT OF THE	A13SE (SE)	5	g	531920 175747
43	Location: 1-3 Classification: Ga Status: Ind	irrectory Entries ty Autos 5, Hinton Road, London, SE24 0HJ arage Services active ntomatically positioned to the address	A13SE (SE)	5	8	531920 175747
43	Location: 7, Classification: Ca Status: Ind	irectory Entries stes Catering Hinton Road, London, SE24 0HJ stering Equipment active utomatically positioned to the address	A13SE (SE)	5	8	531920 175747
43	Location: Un Classification: Ca Status: Ind	irectory Entries apid Recovery iit 6,8,Higgs Ind Est,Herne Hill Rd, London, SE24 0AU ar Breakdown & Recovery Services active anually positioned to the address or location	A13SE (SE)	35	8	531953 175744
43	Contemporary Trade D Name: Ra Location: Ur Classification: Br Status: Ina		A13SE (SE)	36	2	531954 175745



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
43	Contemporary Trad Name: Location: Classification:	Rapid Recovery Repair Unit 6/8, Higgs Industrial Estate, Heme Hill Road, London, SE24 0AU Car Breakdown & Recovery Services	A13SE (SE)	36	×	531954 175745
		Inactive Manually positioned to the address or location				
43	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Four Point Industries Ltd Unit 5, Higgs Industrial Estate, Heme Hill Road, London, SE24 0AU Seating Manufacturers Inactive Automatically positioned to the address	A13SE (E)	71	я	531989 175750
44	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Lomac Engineering Co Ltd 215-217, Coldharbour Lane, London, SW9 8RU Engineers - General Inactive Automatically positioned to the address	A13NE (N)	4	©.	531912 175780
44	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Metal Artefacts 210, Coldharbour Lane, London, SW9 8SA Gate Manufacturers Inactive Automatically positioned to the address	A13NE (N)	38	*	531914 175825
44	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Marden Taxi Garage 4-6 Rathgar Rd, London, SW9 7EL Garage Services Inactive Manually positioned to the road within the address or location	A13NW (NW)	45	s	531874 175826
44	Contemporary Trad Name: Location: Classification: Status:		A13NW (N)	57	0	531879 175842
45	Contemporary Trad Name: Location: Classification: Status:		A13NW (W)	47	ъ	531844 175782
45	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Super Dry Cleaners 228, Coldharbour Lane, London, SW9 8SD Dry Cleaners Inactive Automatically positioned to the address	A13NW (W)	47	×	531844 175782
46	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries C & C Panels 20-28, Hinton Road, London, SE24 0HJ Car Body Repairs Inactive Automatically positioned to the address	A13SE (S)	58	s	531926 175683
46	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Mayflower Mg & Vw Services Ltd 20-28, Hinton Road, London, SE24 0HJ Garage Services Inactive Automatically positioned to the address	A13SE (S)	58	s	531926 175683
46	Contemporary Trad Name: Location: Classification: Status; Positional Accuracy:	e Directory Entries Wellfit Services 1, Wellfit Street, London, SE24 0JA Garage Services Inactive Automatically positioned to the address	A13SE (SE)	74	Si Si	531962 175684
46	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Wellfit House Of Tyres Ltd 1, Wellfit Street, London, SE24 0JA Tyre Dealers Inactive Automatically positioned to the address	A13SE (SE)	74	Ж	531962 175684



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
	Contemporary Trad	le Directory Entries		×	4 3	0
46	Name: Location: Classification: Status: Positional Accuracy:	Wellfit House Of Tyres Wellfit St, London, SE24 0JA Tyre Repairs & Retreading Inactive Manually positioned within the geographical locality	A13SE (SE)	74	(#F)	531962 175684
*	Contemporary Trad	e Directory Entries				
47	Name: Location: Classification: Status: Positional Accuracy:	Arbo Ltd Unit 9, Higgs Industrial Estate, Heme Hill Road, London, SE24 0AU Cabinet Makers Inactive Automatically positioned to the address	A13NE (NE)	63	i i t	531964 175815
	Contemporary Trad	e Directory Entries				
47	Name: Location: Classification: Status: Positional Accuracy:	Memory Makers Ltd Unit 9, Higgs Industrial Estate, Heme Hill Road, London, SE24 0AU Ceramic Manufacturers, Supplies & Services Inactive Automatically positioned to the address	A13NE (NE)	63	183	531964 175815
	Contemporary Trad	le Directory Entries			9	9
47	Name: Location: Classification: Status: Positional Accuracy:	Portslade Garage Services 1, Heme Hill Road, London, SE24 0AU Garage Services Inactive Manually positioned to the address or location	A13NE (NE)	92	323	531998 175818
7	Contemporary Trad	le Directory Entries	i was a second	2	6	0
48	Name: Location:	Green Oil Unit 202, Shakespeare Business Centre, 245a, Coldharbour Lane, London, SW9 8RR	A13SW (S)	73	H E H	531874 175678
	Classification: Status: Positional Accuracy:	Lubricant Manufacturers & Distributors Active Automatically positioned to the address				
	Contemporary Trade Directory Entries					
48	Name: Location:	G S L Cleaning Unit S7a, Shakespeare Business Centre, 245a, Coldharbour Lane, London, SW9 8RR	A13SW (S)	73	323	531873 175679
	Classification: Status:	Commercial Cleaning Services Active Automatically positioned to the address				
-	Contemporary Trad			5:		<u> </u>
48	Name: Location: Classification: Status:	Enko 245, Coldharbour Lane, London, SW9 8RR Commercial Cleaning Services Inactive	A13SW (S)	73	848	531874 175678
,		Automatically positioned to the address				
48	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	Advanced Shakespeare Business Centre,245a Coldharbour La, London, SW9 8RR Car Accessories Manufacturers Inactive Manually positioned to the address or location	A13SW (S)	73	इडिय	531873 175678
_	Contemporary Trad	philodesconder Military endows the account of the contract of		-	2	*
48	Name: Location: Classification: Status:	King Of Garments Shakespeare Business Centre, 245a, Coldharbour Lane, London, SW9 8RR Dry Cleaners Inactive Manually positioned to the address or location	A13SW (S)	73	525	531874 175678
_	Contemporary Trade Directory Entries					ů-
48	Name: Location: Classification: Status:	First Western Corporation Shakespeare Business Centre 245a, Coldharbour Lane, London, SW9 8RR Recycling Services Inactive Automatically positioned to the address	A13SW (S)	73	J a	531874 175678
	Company of the compan	3		5:	-	2
49	Contemporary Trad Name: Location: Classification: Status:	Auto Care Arch 496a, Rathgar Road, London, SW9 7EP Garage Services Inactive Automatically positioned to the address	A13NW (N)	79	888	531882 175866



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR	
49	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Lewis Ductwork Arch 450, Rathgar Road, London, SW9 7EP Ventilators & Ventilation Systems Active Automatically positioned to the address	A13NW (N)	79 -		531882 175866	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Deans Car Care 505, Arches, Ridgeway Road, London, SW9 7EX Garage Services Inactive Automatically positioned to the address	A13SW (W)	88	F	531806 175744	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Deans Car Care 505, Arches, Ridgeway Road, London, SW9 7EX Garage Services Inactive Automatically positioned to the address	A13SW (W)	88	٠	531806 175744	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Dean'S Car Care 505, Arches, Ridgeway Road, London, SW9 7EX Car Body Repairs Inactive Automatically positioned to the address	A13SW (W)	88	\$##.	531806 175744	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Paramount London Ltd Arch 15-25, Belinda Road, London, SW9 7DT Scrap Metal Merchants Inactive Automatically positioned to the address	A13SW (SW)	89	.5.	531829 175704	
50	Contemporary Trad Name: Location: Classification: Status:		A13SW (SW)	91		531818 175715	
50	Contemporary Trad Name: Location: Classification: Status:		A13SW (W)	92		531803 175740	
50	Contemporary Trad Name: Location: Classification: Status:	Service and the contract of th	A13SW (SW)	96	(20)	531814 175713	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Euroride Associates Belinda Rd, London, SW9 7DT Car Painters & Sprayers Inactive Manually positioned to the road within the address or location	A13SW (SW)	97	25	531814 175711	
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Boni Car Cleaning 507, Arches, Ridgeway Road, London, SW9 7EX Garage Services Inactive Automatically positioned to the address	A13SW (W)	99	8	531799 175733	
50	Contemporary Trad Name: Location: Classification: Status:		A13SW (W)	103	(259)	531795 175732	
50	Contemporary Trad Name: Location: Classification: Status:		A13SW (SW)	105		531808 175706	



Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
50	Contemporary Trad Name: Location: Classification: Status:	le Directory Entries Breakdown & Recovery 508, Arches, Ridgeway Road, London, SW9 7EX Car Body Repairs Active	A13SW (W)	106	설	531794 175728
50	Positional Accuracy: Contemporary Trad Name:	Automatically positioned to the address le Directory Entries J B M Motors	A13SW	106	~	531794
	Location: Classification: Status: Positional Accuracy:	508, Arches, Ridgeway Road, LONDON, SW9 7EX Commercial Vehicle Bodybuilders & Repairers Inactive Automatically positioned to the address	(W)			175728
	Contemporary Trad	le Directory Entries	, N=	- 8		
50	Name: Location: Classification: Status: Positional Accuracy:	E & R Auto Repairs 509, Arches, Ridgeway Road, London, SW9 7EX Car Body Repairs Inactive Automatically positioned to the address	A13SW (W)	113	2	531788 175722
	Contemporary Trad	le Directory Entries				
50	Name: Location: Classification: Status: Positional Accuracy:	2 Ms Auto Repairs 511, Arches, Ridgeway Road, London, SW9 7EX Mechanical Engineers Inactive Automatically positioned to the address	A13SW (W)	125	¥	531779 175713
	Contemporary Trad	e Directory Entries				
50	Name: Location: Classification: Status:	Serviautos 279 Belinda Rd, London, SW9 7DT Car Body Repairs Inactive	A13SW (SW)	135	20	531783 175689
		Manually positioned within the geographical locality	18 3	· · · · · · · · · · · · · · · · · · ·	- 3	8
50	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entires Bin Hygiene Services 273 Belinda Road, London, SW9 7DT Hygiene & Cleansing Services Active Manually positioned within the geographical locality	A13SW (SW)	135	≅	531783 175689
	Contemporary Trade Directory Entries					
51	Name: Location: Classification: Status:	K & S Engineering Ltd Unit 1, Hardess Street, LONDON, SE24 0HN Engineers - General Active Automatically positioned to the address	A13SE (SE)	93		531996 175693
	Contemporary Trad	le Directory Entries	*	**		X
51	Name: Location: Classification: Status: Positional Accuracy:	Robson & Francis Rewinds Unit 2, Hardess Street, London, SE24 0HN Electric Motor Sales & Service Active Automatically positioned to the address	A13SE (SE)	93	*	531996 175693
	Contemporary Trad	e Directory Entries				1
51	Name: Location: Classification: Status: Positional Accuracy:	Qucoat Ltd Unit 3, Hardess Street, London, SE24 0HN Powder Coatings Inactive Automatically positioned to the address	A13SE (SE)	93		531996 175693
ncentr	Contemporary Trad	le Directory Entries	33	: 2000000 E		do
51	Name: Location: Classification: Status: Positional Accuracy:	Austin'S Garage Railway Arch, 254-255, Hardess Street, London, SE24 0HN Garage Services Active Automatically positioned to the address	A13SE (E)	102	×	532018 175729
	Contemporary Trad	le Directory Entries				
52	Name: Location: Classification: Status:	Alpha Auto Centre 1, Herne Hill Road, London, SE24 0AU Garage Services Active	A13NE (E)	117	8	532035 175787
		Automatically positioned to the address		×		S
52	Contemporary Trad Name: Location: Classification: Status:	le Directory Entries Andrews 5-9, Herne Hill Road, London, SE24 0AU Garage Services Inactive	A13NE (E)	126	*	532045 17576




Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
52	Contemporary Trad Name: Location: Classification: Status:	e Directory Entries Personal Print 5-9, Herne Hill Road, London, SE24 0AU Printers Inactive Manually positioned to the address or location	A13NE (E)	126	2	532045 175767
53	Contemporary Trad Name: Location: Classification: Status:		A13SE (SE)	123	6	531975 175633
54	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries J Connolly & Sons 2-22, Padfield Road, London, SE5 9AA Waste Disposal Services Active Automatically positioned to the address	A13NE (NE)	126	22	532027 175836
54	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Andrews Garage 1, Padfield Road, London, SE5 9AA Garage Services Inactive Automatically positioned to the address	A13NE (NE)	151	Œ	532047 175852
55	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries Auto Care 460, Rathgar Road, London, SW9 7EP Garage Services Inactive Automatically positioned to the address	A13NW (N)	127	s	531892 175916
55	Contemporary Trad Name: Location: Classification: Status:		A13NW (N)	127	2	531892 175916
56	Contemporary Trad Name: Location: Classification: Status:		A13NE (NE)	133		531991 175887
57	Contemporary Trad Name: Location: Classification: Status:	The Control of the Co	A13NE (NE)	186	*	532078 175867
58	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries North Brixton Motor Co 31-35, Padfield Road, London, SE5 9AA Garage Services Inactive Automatically positioned to the address	A13NE (E)	188	5.	532108 175771
58	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	e Directory Entries F W Cherry & Son 31-35, Padfield Road, London, SE5 9AA Garage Services Inactive Automatically positioned to the address	A13NE (E)	188	*	532108 175771
58	Contemporary Trad Name: Location: Classification: Status;	estation and control ★ • Chicago and Chair * Secretarion Chair Vs.	A13NE (E)	188	¥	532108 175771
58	Contemporary Trad Name: Location: Classification: Status:		A13NE (E)	188	=	532108 175771




Map ID		Details	Quadrant Reference (Compass Direction)	Estimated Distance From Site	Contact	NGR
59	Name: Location: Classification: Status:	le Directory Entries Lambeth Pest Control Department 26, Wanless Road, London, SE24 0HW Pest & Vermin Control Inactive Automatically positioned to the address	A13SE (E)	202		532119 175722
60	Contemporary Trad Name: Location: Classification: Status:	Maria de Caración	A13SW (SW)	214	583	531723 175636
61	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Stay Clean Cleaning Co 45, Hinton Road, London, SE24 0HR Commercial Cleaning Services Inactive Automatically positioned to the address	A13SE (SE)	215	i.e	532063 175583
62	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Madeira Cleaning Services Ltd 39, Herne Hill Road, London, SE24 0AX Commercial Cleaning Services Inactive Automatically positioned to the address	A13SE (SE)	229	386	532134 175668
63	Name: Location: Classification: Status:	le Directory Entries The Auto Shop Railway Arch 444, Wickwood Street, London, SE5 9DW Garage Services Active Automatically positioned to the address	A13NE (N)	231	1341	531910 176021
64	Contemporary Trad Name: Location: Classification: Status:		A13NW (N)	238		531851 176023
65	Contemporary Trad Name: Location: Classification: Status:	The Annual Control of	A13NE (NE)	271	140	532136 175934
66	Contemporary Trad Name: Location: Classification: Status:	le Directory Entries T D Graphics 26-34, Southwell Road, London, SE5 9PG Printers Inactive Automatically positioned to the address	A13NE (E)	277	**	532176 175875
66	Contemporary Trad Name: Location: Classification: Status: Positional Accuracy:	le Directory Entries Macey Print Finishers Ltd 26-34, Southwell Road, London, SE5 9PQ Print Finishers Inactive Automatically positioned to the address	A13NE (E)	277	125	532176 175875
66	Name: Location: Classification: Status:	le Directory Entries Supreme Die Cutters 26-34, Southwell Road, London, SE5 9PQ Print Finishers Inactive Automatically positioned to the address	A13NE (E)	277	383	532176 175875
66	Contemporary Trad Name: Location: Classification: Status:	le Directory Entries Leading Lights Of London Ltd 38a, Southwell Road, London, SE5 9PG Stained Glass Designers & Producers Active Automatically positioned to the address	A13NE (NE)	304	16	532197 175895
67	Contemporary Trad Name: Location: Classification: Status:	le Directory Entries A G M Transport 42, Kemerton Road, London, SE5 9AR Road Haulage Services Inactive Automatically positioned to the address	A13SE (E)	291	2.0	532195 175654

Appendix E – Historical Maps


© Crown copyright. All rights reserved. Licence number LAN1001467.




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd


0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd

Contaminated Land Solutions


0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd

Contaminated Land Solutions


0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd




0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd



0973-P1E-1: 219-223 Coldharbour Lane, Brixton Coldharbour Lane Ltd

Appendix G – Contacts

	Building Control	t	
		е	
Lasal Assilassitas		w	
Local Authority	Environmental Health	t	
		е	
		W	
	National Customer Contact Centre	t	08708 506 506
Environment	PO Box 544	е	
Agency	Rotherham	w	enquiries@environment-
	S60 1BY		agency.gov.uk
	Mining Reports Office	t	
Coal Authority	200 Lichfield Lane	е	
Coal Additionty	Berry Hill, Mansfield	W	www.coalminingreports
	Notts, HG18 4RG		<u>.co.uk</u>
Health Protection	Chilton	t	01235 822622
Agency, Radiation	Didcot	е	radon@hpa.org.uk
Protection	Oxon, OX11 0RQ	w	
Division	www.hpa.org.uk/radiation		

Appendix H - References

1. Cover systems for land regeneration - thickness of cover systems for contaminated land, by P Tedd, P Witherington, D Earle, S Hollingsworth, B Furlong, L Bradley, H Mallett, D Laidler, BRE publication dated Mar 22, 2004