



CERTIFICATE FOR IDENTIFICATION OF ASBESTOS FIBRES

| | |
|-----------|--------------------------|
| STANDARD | <input type="checkbox"/> |
| PREMIUM | <input type="checkbox"/> |
| EMERGENCY | <input type="checkbox"/> |

| | | | | | |
|-----------------------|---|---------------------|--------------|----------|----|
| Client: | S&K ENVIRONMENTAL SOLUTIONS LTD | Analysis Report No. | SCO/15/29836 | | |
| Address: | UNIT 11 WEST POINT PLACE KINGS ROAD CHARFLEET CANVEY ISLAND SS8 0SE | | Report Date. | 07/10/15 | |
| Attention: | SIMON BATCHELOR | Site Ref No. | N/A | | |
| Site Address: | THE QUEENSBURY PUB 110 WALM LANE WILLES DEN GREEN LONDON NW2 | | Page No: | 1 | Of |
| Date sample taken: | 07/10/15 | No. of Samples: | 17 | | |
| Date sample received: | 07/10/15 | Obtained: | DELIVERED | | |
| Date of Analysis: | 07/10/15 | | | | |

Samples of material, referenced below, have been examined to determine the presence of asbestos fibres, using Scopes Asbestos Analysis "in house" method of transmitted/polarised light microscopy and centre stop dispersion staining, based on HSE's HSG248. If samples have been DELIVERED the site address and actual sample location is as given by the client at the time of delivery. Scopes Asbestos Analysis Services Limited are not responsible for the accuracy or competence of the sampling by third parties. Under these circumstances Scopes Asbestos Analysis Services Limited cannot be held responsible for the interpretation of the results shown.

| SCOPE SAMPLE No. | CLIENT SAMPLE No. | Sample Location | Fibre Type Detected |
|------------------|-------------------|--|-------------------------------------|
| 1 | IP/01 | ROOM 8- FEMALE W/C- BITUMEN UNDER CERAMIC FLOOR TILES | NADIS |
| 2 | IP/02 | ROOM 7- FEMALE W/C FOYER- PUTTY TO GLASS VIEWING PANEL IN DOOR | NADIS |
| 3 | IP/03 | ROOM 13- DANCE FLOOR- CEILING TILES IN SUSPENDE D CEILING | NADIS |
| 4 | IP/04 | ROOM 14- FLOOR TILES AND BITUMEN | CHRY SOTILE TO BITUMEN BACKING ONLY |
| 5 | IP/05 | ROOM 13- DANCE FLOOR- VINYL FLOORING UNDER CARPET | NADIS |
| 6 | IP/07 | ROOM 16- BAR AREA- CEILING TILES ABOVE EXISTING CEILING TILES | NADIS |
| 7 | IP/08 | ROOM 16- BAR AREA- LINO UNDER CARPET | NADIS |
| 8 | IP/09 | ROOM 16- BAR AREA- BITUMEN UNDER LINO AND CARPET | NADIS |
| 9 | IP/10 | ROOM 17- BAR AREA- LINO AND BITUMEN UNDER CARPET | NADIS |
| 10 | IP/11 | ROOM 18- BAR- VERMICULITE COATING TO WORK SURFACE BEHIND BAR | NADIS |

KEY: NADIS - No Asbestos Detected in Sample

Note: All samples will be retained for a minimum of six months.

Note: This Certificate for Identification of Asbestos Fibres shall not be reproduced except in full without the written approval of the Laboratory.

| | | | |
|--------------|--------|-----------------------|-----------------|
| Analysed by: | M ZHOU | Authorised signatory: | |
| | | Print name: | S BOLTON- Q.C.M |

BULK 001-VER 5 12-AUGUST-09-QCM



CERTIFICATE FOR IDENTIFICATION OF ASBESTOS FIBRES

| | |
|-----------|--------------------------|
| STANDARD | <input type="checkbox"/> |
| PREMIUM | <input type="checkbox"/> |
| EMERGENCY | <input type="checkbox"/> |

| | | | | | |
|-----------------------|---|---------------------|--------------|----------|---|
| Client: | S&K ENVIRONMENTAL SOLUTIONS LTD | Analysis Report No. | SCO/15/29836 | | |
| Address: | UNIT 11 WEST POINT PLACE KINGS ROAD CHARFLEET CANVEY ISLAND SS8 0SE | | Report Date. | 07/10/15 | |
| Attention: | SIMON BATCHELOR | Site Ref No. | N/A | | |
| Site Address: | THE QUEENSBURY PUB 110 WALM LANE WILLESDEN GREEN LONDON NW2 | Page No: | 2 | Of | 2 |
| Date sample taken: | 07/10/15 | No. of Samples: | 17 | | |
| Date sample received: | 07/10/15 | Obtained: | DELIVERED | | |
| Date of Analysis: | 07/10/15 | | | | |

Samples of material, referenced below, have been examined to determine the presence of asbestos fibres, using Scopes Asbestos Analysis "in house" method of transmitted/polarised light microscopy and centre stop dispersion staining, based on HSE's HSG248. If samples have been DELIVERED the site address and actual sample location is as given by the client at the time of delivery. Scopes Asbestos Analysis Services Limited are not responsible for the accuracy or competence of the sampling by third parties. Under these circumstances Scopes Asbestos Analysis Services Limited cannot be held responsible for the interpretation of the results shown.

| SCOPE SAMPLE No. | CLIENT SAMPLE No. | Sample Location | Fibre Type Detected |
|------------------|-------------------|---|-----------------------------------|
| 11 | IP/12 | ROOM 18- BAR- VERMICULITE COATING TO SHELVING UNDER BAR | NADIS |
| 12 | IP/14 | ROOMS 20 AND 21- LINO ON CONCRETE FLOOR AND BITUMEN | CHRYSTILE TO BITUMEN BACKING ONLY |
| 13 | IP/15 | ROOM 24- KITCHEN- BITUMEN SINK PADS UNDER SINK UNIT | CHRYSTILE |
| 14 | IP/16 | ROOM 24- KITCHEN- COATING TO PANEL ON WALL | NADIS |
| 15 | IP/17 | ROOM 24- KITCHEN- PANEL ABOVE BOILER COVERING CHIMNEY | AMOSITE/CHRYSTILE |
| 16 | IP/18 | ROOM 26- GARAGE- CEMENT BOARD TO CEILING | CHRYSTILE |
| 17 | IP/19 | ROOM 26- GARAGE- BOARD TO WALL | CHRYSTILE |
| | | | |
| | | | |
| | | | |

KEY: NADIS - No Asbestos Detected in Sample

Note: All samples will be retained for a minimum of six months.

Note: This Certificate for Identification of Asbestos Fibres shall not be reproduced except in full without the written approval of the Laboratory.

| | | | |
|--------------|-------------|-----------------------|------------------------|
| Analysed by: | W JEFFERIES | Authorised signatory: | |
| | | Print name: | S BOLTON- Q.C.M |

BULK 001-VER 5 12-AUGUST-09-QCM